

Table of Contents

Incident Name: CR-251

Period: Initial Re [10/31/16 16:45 - 11/01/16 16:45]

| <i>Report Name</i> | <i>Page</i> |
|--|-------------|
| IAP Cover Sheet | 1 |
| Weather Report | 3 |
| ICS 201-2 - Summary of Current Actions | 4 |
| ICS 201-4 - Resource Summary | 6 |
| ICS 201-5 - Site Safety and Control Analysis | 10 |
| ICS 206 - Medical Plan | 12 |
| ICS 207 - Organization Chart | 13 |

Table of Contents

| | | | | | |
|--|--------------|------------------------------------|--|----------------|-------------------------------------|
| Weather Report | | | Version Name: 20161101_0430 | | |
| Incident Name: CR-251 | | | Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45] | | |
| Present Conditions | | | | | |
| Weather Conditions as of 11/01/2016 04:53 | | | | | |
| Humidity (%): 87 Wind Speed: 0.00 MPH Wind Direction (from): N Temperature: 56.00 F Visibility: 10.00 MI | | | Pressure: 30.12 IN Dew Point: 52.00 Feels Like: 56.00 UV Index: | | |
| Clear | | | | | |
| Forecast Date | Wind | Temp Hi/Lo | % Precip | Sunrise/Sunset | Notes |
| Tue 11/01/2016 | 5.00 MPH ESE | 90.00 F/ F | 0.00 | 07:06 | Sunny |
| | 3.00 MPH SE | F/61.00 F | 0.00 | 17:55 | Mostly Clear |
| Wed 11/02/2016 | 4.00 MPH ESE | 86.00 F/ F | 0.00 | 07:07 | Partly Cloudy |
| | 1.00 MPH SE | F/61.00 F | 0 | 17:54 | Partly Cloudy |
| Thu 11/03/2016 | 4.00 MPH SSW | 84.00 F/ F | 0 | 07:08 | Partly Cloudy |
| | 6.00 MPH NW | F/54.00 F | 0 | 17:53 | Partly Cloudy with Isolated Showers |
| Fri 11/04/2016 | 8.00 MPH N | 75.00 F/ F | 0 | 07:09 | Mostly Sunny |
| | 4.00 MPH N | F/46.00 F | 0.00 | 17:52 | Clear |
| Sat 11/05/2016 | 4.00 MPH NNE | 75.00 F/ F | 0.00 | 07:10 | Mostly Sunny |
| | 3.00 MPH NNE | F/46.00 F | 0.00 | 17:51 | Mostly Clear |
| Tides | | | | | |
| | | | | | |
| Weather Report | | | Prepared By Thompson, Holland, Updated 11/01/2016 05:49 GMT -6 | | |
| INCIDENT ACTION PLAN SOFTWARE™ | | Printed 11/01/2016 11:42 GMT -6:00 | | Page 3 of 14 | |
| | | | | © TRG | |

| | | | |
|--|---|---|-------|
| ICS 201-2 - Summary of Current Actions | | Version Name: Initial Response | |
| Incident Name: CR-251 | | Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45] | |
| Initial Response Objectives | | | |
| Ensure the Safety of Citizens and Response Personnel | | | |
| Manage Coordinated Response Effort | | | |
| Control the Source | | | |
| Maximize Protection of Environmentally-Sensitive Areas | | | |
| Contain and Recover Spilled Material | | | |
| Communicate w/ public and stakeholders | | | |
| Current and Planned Actions | | | |
| Date/Time | Action/Event/Notes | | |
| 10/31/2016 14:55 | Danny Cook called in with the report of a line strike mp 573.7. 770-689-9544 | | |
| 10/31/2016 15:00 | Line 1 and 2 shutdown | | |
| 10/31/2016 15:02 | VAB MLBV closed | | |
| 10/31/2016 15:05 | PLJ MLBV closed | | |
| 10/31/2016 15:06 | OXB MLBV closed | | |
| 10/31/2016 15:07 | EPB MLBV closed | | |
| 10/31/2016 15:07 | Moundville MLBV Closed - Line 1 | | |
| 10/31/2016 15:25 | US manual isolation valve closed at the PLJ01 cooling tower | | |
| 10/31/2016 15:44 | PLJ01 hydraulics turned off to MLBV and Discharge valve, Valves closed | | |
| 10/31/2016 15:50 | Crews headed to closed the manual block valves | | |
| 10/31/2016 15:56 | NRC report submitted #1162982 | | |
| 10/31/2016 16:02 | ADEM notified - Zakiya Darry Inc#16-1099 (JW made notice) | | |
| 10/31/2016 16:30 | Rachel Gunaratnam called in from the NTSB with questions about injuries and the type of work we were doing. | | |
| 10/31/2016 16:30 | Group 8 sent per Angie Kolar | | |
| 10/31/2016 16:36 | West Side Cahaba River valve closed. Valve 498490 | | |
| 10/31/2016 17:00 | Incident Command Post set up at Valley Elementary School (310 Opportunity Drive, Pelham, AL 35124) | | |
| 10/31/2016 17:25 | VAB01 DS isolation valve 408609 is closed. Hydraulics turned off to VAB01 MLBV and Discharge valve. | | |
| 10/31/2016 18:09 | Downstream Cahaba River valve 505500 is closed and locked out. | | |
| 10/31/2016 18:10 | Command Center is at Valley Elementary School, 310 Opportunity Dr, Pelham AL 35124 | | |
| 10/31/2016 19:00 | FOBS @ Living river org - contact Dana Byrd 205-283-5440 OSROS EN route (ETA: unknown at ths time) | | |
| 10/31/2016 19:19 | HEPACO in route to AL-17a-1 to deploy boom (eta 21:00) (Billy Morton - Supervisor) | | |
| 10/31/2016 20:00 | CTEH Began Air Monitoring, 4 POB/2 vehicles | | |
| 10/31/2016 22:00 | HEPACO arrived at AL-17a-1 (CPC - Jeff Stewart-Project inspector) | | |
| 10/31/2016 22:50 | Line 2 restarted | | |
| 10/31/2016 22:50 | Renamed incident in IC/UC Objectives Meeting (Changed to CR-251) | | |
| 10/31/2016 23:24 | Complete install of boom at AL-17A1 consisting of: 100' Cascading boom to collection point 240' Containment boom 240' soft boom in front of containment boom | | |
| 11/01/2016 03:25 | 200' of hard boom installed at Living River Boom Site #1 and two vac trucks on site. | | |
| 11/01/2016 05:28 | 300' of hard boom installed and 300' of soft boom installed at Living River Boom Site #3 and two vac trucks on site. | | |
| 11/01/2016 09:00 | OPERATIONS Unit Log: Cazares, Juan -- OSHA is on site and ready to support. | | |
| ICS 201-2 - Summary of Current Actions | | Prepared By Terri Arnold, Updated 11/01/2016 11:10 GMT -6:00 PP | |
| INCIDENT ACTION PLAN SOFTWARE™ | Printed 11/01/2016 11:42 GMT -6:00 | Page 4 of 14 | © TRG |

| | | | |
|---|--|---|-------|
| ICS 201-2 - Summary of Current Actions | | Version Name: Initial Response | |
| Incident Name: CR-251 | | Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45] | |
| 11/01/2016 09:57 | Staging area identified; 20105 Hwy 11 Woodstock AI 35188 | | |
| <i>Approved By</i> | | | |
| Incident Commander: | | Date: | |
| | | | |
| ICS 201-2 - Summary of Current Actions | | Prepared By Terri Arnold, Updated 11/01/2016 11:10 GMT -6:00 PP | |
| INCIDENT ACTION PLAN SOFTWARE™ | Printed 11/01/2016 11:42 GMT -6:00 | Page 5 of 14 | © TRG |

ICS 201-4 - Resource Summary

Incident Name: CR-251

Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45]

| ID | Resource | | | Ordered | ETA | Arrived | Area Of Operation |
|----|-----------|--|-------------------------------------|------------------|------------------|-------------------------------------|---------------------------|
| | Quantity | Kind/Description | Supplier | | | | |
| 80 | 100 feet | Boom: Cascade Boom | Hepaco | 11/01/2016 02:13 | | <input type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 78 | 340 feet | Boom: Hard Boom | Hepaco | 11/01/2016 02:12 | | <input checked="" type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 84 | 4 each | Jon Boat: Jon Boat | Hepaco | 11/01/2016 02:22 | | <input checked="" type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 76 | 1 each | Light Plants: Light Plant | Hepaco | 11/01/2016 02:09 | | <input checked="" type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 75 | 7 each | Manpower: Responder: Responder | Hepaco | 11/01/2016 02:08 | | <input checked="" type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 81 | 6 each | Pickup Truck: Pickup Truck | Hepaco | 11/01/2016 02:15 | | <input type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 79 | 240 feet | Sorbent: Boom: Sorbent Boom | Hepaco | 11/01/2016 02:12 | | <input type="checkbox"/> | AL-17A-1 Recovery Site TF |
| 82 | 2 each | Manpower: Responder: Responder | William's Fire & Hazard Control Inc | 11/01/2016 02:17 | 11/01/2016 12:00 | <input type="checkbox"/> | Fire Suppression TF |
| 4 | 1000 feet | Boom: 12" - 18" Hard Boom | Hepaco | | 10/31/2016 21:34 | <input type="checkbox"/> | Incident Location |
| 12 | 1000 feet | Boom: 12" - 18" Hard Boom | Hepaco | | 10/31/2016 21:34 | <input type="checkbox"/> | Incident Location |
| 13 | 1 each | Jon Boat: Jon Boat with Motor | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 5 | 1 each | Jon Boat: Jon Boat with Motor | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 27 | 4 each | Manpower: Operator: Truck Driver | Hepaco | | 10/31/2016 21:55 | <input type="checkbox"/> | Incident Location |
| 26 | 2 each | Manpower: Supervisor: Operations Foreman | Hepaco | | 10/31/2016 21:54 | <input type="checkbox"/> | Incident Location |
| 25 | 6 each | Manpower: Supervisor: Technician | Hepaco | | 10/31/2016 21:50 | <input type="checkbox"/> | Incident Location |
| 6 | 1 each | Vehicle: Pickup Truck | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 7 | 1 each | Vehicle: Pickup Truck | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 8 | 1 each | Vehicle: Pickup Truck | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 14 | 1 each | Vehicle: Pickup Truck | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 15 | 1 each | Vehicle: Pickup Truck | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 16 | 1 each | Vehicle: Pickup Truck | Hepaco | | 10/31/2016 21:37 | <input type="checkbox"/> | Incident Location |
| 20 | 1000 feet | Boom: Containment Boom 18" | SWS Environmental Services | | 10/31/2016 21:48 | <input type="checkbox"/> | Incident Location |
| 19 | 1 each | Emergency Response Trailer: Emergency Response Trailer | SWS Environmental Services | | 10/31/2016 21:30 | <input type="checkbox"/> | Incident Location |
| 33 | 2 each | Manpower: Operator: Equipment Operator | SWS Environmental Services | | 10/31/2016 22:18 | <input type="checkbox"/> | Incident Location |
| 28 | 3 each | Manpower: Responder: Technician | SWS Environmental Services | | 10/31/2016 22:09 | <input type="checkbox"/> | Incident Location |
| 29 | 1 each | Manpower: Supervisor: Operations Foreman | SWS Environmental Services | | 10/31/2016 22:10 | <input type="checkbox"/> | Incident Location |
| 22 | 1 each | Vehicle: Pickup Truck | SWS Environmental Services | | 10/31/2016 21:49 | <input type="checkbox"/> | Incident Location |

ICS 201-4 - Resource Summary

ICS 201-4 - Resource Summary

Incident Name: CR-251

Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45]

| ID | Resource | | | Ordered | ETA | Arrived | Area Of Operation |
|-----|------------|--|----------------------------------|------------------|------------------|-------------------------------------|--------------------------------|
| | Quantity | Kind/Description | Supplier | | | | |
| 23 | 1 each | Vehicle: Pickup Truck | SWS Environmental Services | | 10/31/2016 21:49 | <input type="checkbox"/> | Incident Location |
| 24 | 1 each | Vehicle: Pickup Truck | SWS Environmental Services | | 10/31/2016 21:49 | <input type="checkbox"/> | Incident Location |
| 1 | 1 each | Vacuum Truck: Vacuum Truck (3000 - 3500 gal) | Hepaco | | 10/31/2016 21:26 | <input checked="" type="checkbox"/> | LR-3 Recovery Site TF |
| 2 | 1 each | Vacuum Truck: Vacuum Truck (3000 - 3500 gal) | Hepaco | | 10/31/2016 21:26 | <input checked="" type="checkbox"/> | LR-3 Recovery Site TF |
| 9 | 1 each | Vacuum Truck: Vacuum Truck (3000 - 3500 gal) | Hepaco | | 10/31/2016 21:26 | <input checked="" type="checkbox"/> | LR-3 Recovery Site TF |
| 10 | 1 each | Vacuum Truck: Vacuum Truck (3000 - 3500 gal) | Hepaco | | 10/31/2016 21:26 | <input checked="" type="checkbox"/> | LR-3 Recovery Site TF |
| 87 | 5 each | Frac Tank: Frac Tank | SWS Environmental Services | 11/01/2016 02:27 | | <input type="checkbox"/> | LR-3 Recovery Site TF |
| 73 | 4 each | Manpower: Supervisor: Responder | Colonial Pipeline | 11/01/2016 02:03 | | <input checked="" type="checkbox"/> | Protection and Recovery Branch |
| 69 | 2000 feet | Boom: Hard Boom | SWS Environmental Services | 11/01/2016 01:57 | | <input type="checkbox"/> | Protection and Recovery Branch |
| 70 | 1700 feet | Boom: Soft Boom | SWS Environmental Services | 11/01/2016 01:58 | | <input type="checkbox"/> | Protection and Recovery Branch |
| 40 | 6 each | Light Tower: Light Tower | SWS Environmental Services | | 10/31/2016 22:34 | <input checked="" type="checkbox"/> | Protection and Recovery Branch |
| 74 | 9 each | Manpower: Responder: Responder | SWS Environmental Services | 11/01/2016 02:04 | | <input type="checkbox"/> | Protection and Recovery Branch |
| 72 | 1 each | Vacuum Truck: Vacuum Truck, 2500 Gallon | SWS Environmental Services | | 10/31/2016 21:45 | <input type="checkbox"/> | Protection and Recovery Branch |
| 17 | 1 each | Vacuum Truck: Vacuum Truck, 2500 Gallon | SWS Environmental Services | | 10/31/2016 21:45 | <input checked="" type="checkbox"/> | Protection and Recovery Branch |
| 18 | 1 each | Vacuum Truck: Vacuum Truck, 2500 Gallon | SWS Environmental Services | | 10/31/2016 21:45 | <input checked="" type="checkbox"/> | Protection and Recovery Branch |
| 21 | 3 each | Vessel: Jon Boat | SWS Environmental Services | | 10/31/2016 21:48 | <input checked="" type="checkbox"/> | Protection and Recovery Branch |
| 77 | 560 feet | Boom: Hard Boom | Hepaco | 11/01/2016 02:10 | | <input checked="" type="checkbox"/> | Staging Area |
| 85 | 2 each | Boom Trailer: Boom Trailer | Hepaco | 11/01/2016 02:23 | | <input type="checkbox"/> | Staging Area |
| 3 | 1 each | Emergency Response Trailer: Emergency Response Trailer | Hepaco | | 10/31/2016 21:30 | <input checked="" type="checkbox"/> | Staging Area |
| 11 | 1 each | Emergency Response Trailer: Emergency Response Trailer | Hepaco | | 10/31/2016 21:30 | <input checked="" type="checkbox"/> | Staging Area |
| 86 | 15 bale(s) | Sorbent: Diapers | Hepaco | 11/01/2016 02:24 | | <input type="checkbox"/> | Staging Area |
| 83 | 760 feet | Sorbent: Boom: Sorbent Boom | Hepaco | 11/01/2016 02:19 | | <input checked="" type="checkbox"/> | Staging Area |
| 246 | 1 each | Vehicle: Fire Engine: Fire Engine 821 | Indian Ford | 11/01/2016 09:52 | | <input type="checkbox"/> | Staging Area |
| 249 | 1 each | Vehicle: Fire Engine: Fire Tanker 830 | Indian Ford | 11/01/2016 09:52 | | <input type="checkbox"/> | Staging Area |
| 223 | 1 each | Air Compressor: CFM Compressor | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 247 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 193 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 194 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |

ICS 201-4 - Resource Summary

ICS 201-4 - Resource Summary

Incident Name: CR-251

Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45]

| ID | Resource | | | Ordered | ETA | Arrived | Area Of Operation |
|-----|----------|---|----------------------------------|------------------|-----|-------------------------------------|-------------------|
| | Quantity | Kind/Description | Supplier | | | | |
| 195 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 196 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 198 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 199 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 201 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 187 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 244 | 1 each | Lighting: Light Tower | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 250 | 1 each | Roll Off Box: Lowboy or Float Trailer | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 263 | 1 each | Tractor: Tract Hoe | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 251 | 1 each | Tractor: Tractor | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 257 | 1 each | Tractor: Tractor | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 261 | 1 each | Trailer: Lowboy or Float Trailer | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 237 | 1 each | Vacuum Unit: F350 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 285 | 1 each | Vehicle: E350 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 287 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 281 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 282 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 283 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 284 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 239 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 240 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 242 | 1 each | Vehicle: F250 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 238 | 1 each | Vehicle: F350 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 205 | 1 each | Vehicle: F350 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 286 | 1 each | Vehicle: F350 | L.E. Bell Construction Co., Inc. | 11/01/2016 11:07 | | <input type="checkbox"/> | Staging Area |
| 216 | 0 each | Vehicle: Flatbed Dump Truck | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 207 | 1 each | Vehicle: MACK TRUCK | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 191 | 1 each | Vehicle: Trailer | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 214 | 1 each | Vehicle: Versa Loader - JCB525-60 | L.E. Bell Construction Co., Inc. | | | <input checked="" type="checkbox"/> | Staging Area |
| 260 | 1 each | Emergency Response Trailer: Pelham Hazmat Trailer | Pelham Fire Department | 11/01/2016 10:05 | | <input type="checkbox"/> | Staging Area |
| 256 | 1 each | Response Truck: Pelham Brush Truck | Pelham Fire Department | 11/01/2016 10:05 | | <input type="checkbox"/> | Staging Area |
| 265 | 1 each | Ambulance: Ambulance | Regional Paramedical Services | 11/01/2016 10:17 | | <input type="checkbox"/> | Staging Area |
| 276 | 1 each | Equipment: Comms: COW - Cellsite on Wheels | Southern LINC | 11/01/2016 10:51 | | <input type="checkbox"/> | Staging Area |

ICS 201-4 - Resource Summary

ICS 201-4 - Resource Summary

Incident Name: CR-251

Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45]

| ID | Resource | | | Ordered | ETA | Arrived | Area Of Operation |
|-----|-----------|--|----------------------------|------------------|------------------|-------------------------------------|-------------------|
| | Quantity | Kind/Description | Supplier | | | | |
| 279 | 1 each | Equipment: Comms: GOAT - Genset on Wheels | Southern LINC | 11/01/2016 10:51 | | <input type="checkbox"/> | Staging Area |
| 280 | 1 each | Equipment: Comms: SOW - Sattelite on Wheels | Southern LINC | 11/01/2016 10:51 | | <input type="checkbox"/> | Staging Area |
| 127 | 1000 feet | Boom: Containment Boom 18" | SWS Environmental Services | | 10/31/2016 21:48 | <input type="checkbox"/> | Staging Area |
| 126 | 1 each | Emergency Response Trailer: Emergency Response Trailer | SWS Environmental Services | | 10/31/2016 21:30 | <input type="checkbox"/> | Staging Area |
| 124 | 1 each | Vacuum Truck: Vacuum Truck, 2500 Gallon | SWS Environmental Services | | 11/01/2016 06:58 | <input checked="" type="checkbox"/> | Staging Area |
| 125 | 1 each | Vacuum Truck: Vacuum Truck, 2500 Gallon | SWS Environmental Services | | 11/01/2016 06:58 | <input checked="" type="checkbox"/> | Staging Area |
| 129 | 1 each | Vehicle: Pickup Truck | SWS Environmental Services | | 10/31/2016 21:49 | <input type="checkbox"/> | Staging Area |
| 130 | 1 each | Vehicle: Pickup Truck | SWS Environmental Services | | 10/31/2016 21:49 | <input type="checkbox"/> | Staging Area |
| 131 | 1 each | Vehicle: Pickup Truck | SWS Environmental Services | | 10/31/2016 21:49 | <input type="checkbox"/> | Staging Area |

ICS 201-4 - Resource Summary

| | | | |
|--|---|---|-------|
| ICS 201-5 - Site Safety and Control Analysis | | Version Name: 20161101 RDO | |
| Incident Name: CR-251 | | Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45] | |
| Site Control | | | |
| 1. Is Site Control set up? Yes | 2. Is there an on-scene command post? Yes | If so, where? Valley Elementary School | |
| 3. Have all personnel been accounted for? Yes | Injuries Unaccounted 4 0 | Fatalities Trapped 1 0 | |
| 4. Are observers involved, or rescue attempts ongoing/planned? | Observers - Yes Rescuers - No | 5. Are decon areas setup? | No |
| Hazard Identification | | | |
| 1. Electrical line(s) down or overhead? Yes Remarks: 400' SSW from site | | 2. Unidentified liquid or solid products visible? No Remarks: | |
| 3. Wind direction across incident Away from your position Wind Speed: 1 mph | | 4. Is a safe approach possible? Yes Remarks: Fire Department controlling access | |
| 5. Odors or smells? Yes Remarks: smoke | | 6. Vapors visible? No Remarks: | |
| 7. Holes, ditches, fast water, cliffs, etc. nearby? No Remarks: | | 8. Fire, sparks, sources of ignition nearby? Yes Remarks: | |
| 9. Is local traffic a potential problem? No Remarks: | | 10. Product placards, color codes visible? No Remarks: | |
| 11. Other hazards? No Remarks: | | 12. As you approach the scene from upwind, do you note a change in the status of any of the above? No Remarks: | |
| Hazard Mitigation | | | |
| 1. Entry Objectives: | | | |
| Ensure public and personnel safety through air monitoring and exclusion zone establishment | | | |
| 2. Warning sign(s), barriers, color codes in place? Yes | | | |
| 3. Hazardous material being monitored? Yes | | | |
| 3a. Sampling Equipment: | | Minican, MultiRAE | |
| 3b. Sampling Locations: | | CR-13, residential areas | |
| 3c. Sampling Frequency: | | once an hour | |
| 3d. Personal Exposure Monitoring: | | N/A | |
| 4. Protective gear/level: | | | |
| 4a. Gloves: | | | |
| 4b. Respirators: | | N/A | |
| 4c. Clothing: | | FR | |
| 4d. Boots: | | Safety Shoes | |
| 4e. Chemical cartridge change frequency: | | N/A | |
| 5. Decon | | | |
| 5a. Instructions: | | N/A | |
| 5b. Decon equipment and materials: | | N/A | |
| 6. Emergency escape route established? Yes | | | |
| 7. Field Responders briefed on hazards? Yes | | | |
| 8. Remarks | | | |
| Only necessary personnel allowed within the Hot Zone if authorized to do so by local fire department | | | |
| ICS 201-5 - Site Safety and Control Analysis | | Prepared By OBrien, Ricky, Updated 11/01/2016 07:36 GMT -6:00 PP | |
| INCIDENT ACTION PLAN SOFTWARE™ | Printed 11/01/2016 11:42 GMT -6:00 | Page 10 of 14 | © TRG |


| | | | | | | | | |
|---|---|-------------------------------------|-------------------|---|-------------------------------------|------------------|-------------------------------------|-------------------------------------|
| ICS 206 - Medical Plan | | | | Version Name: 20161101 DFJ | | | | |
| Incident Name: CR-251 | | | | Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45] | | | | |
| Medical Aid Stations | | | | | | | | |
| Name | Location | Paramedic On Site | Phone | Radio | | | | |
| Pelham and Fire Department | Street Helena, AL 35080 -87.00604 33.20369 | <input checked="" type="checkbox"/> | Ph1: 205.369.1467 | | | | | |
| Transportation (Ground and/or Air Ambulance Services) | | | | | | | | |
| Ambulance Service | Location | Phone | Radio | Air | ALS | | | |
| RPS Ambulance Service | -87.00639 33.20425 | Ph1: On Site | | <input type="checkbox"/> | <input checked="" type="checkbox"/> | | | |
| TCP - Lifesaver | -87.00639 33.20425 | Ph1: 205-324-1066 | | <input checked="" type="checkbox"/> | <input type="checkbox"/> | | | |
| Hospitals | | | | | | | | |
| Hospital | Location | Phone | Radio | Air Travel Time | Ground Travel Time | Trauma Center | Helipad | Burn Center |
| Shelby Baptist Medical Center | 1000 First Street North Alabaster, AL 35007 -86.8141 33.2544 | Ph1: 205-620-8100 | | 15 min | 30 min | III | <input checked="" type="checkbox"/> | <input type="checkbox"/> |
| UAB Hospital | 1802 6th Avenue South Birmingham, AL 35233 -84.14655 33.8055 | Ph1: 205-934-5100 | | 15 min | 45 min | I | <input checked="" type="checkbox"/> | <input checked="" type="checkbox"/> |
| Special Medical Emergency Procedures | | | | | | | | |
| <p>RPS Ambulance Service, Pelham and Helena Fire Department are on site at the staging area -at a minimum 1 ambulance (1 paramedic 1 EMT)</p> <p>Pelham Fire EMS supplying mobile rehab also has a decon in staging.</p> <p>Fire Departments will coordinate air ambulance service if needed.</p> | | | | | | | | |
| Approved By | | | | | | | | |
| <p>Safety officer: _____ Date: _____</p> | | | | | | | | |
| | | | | | | | | |
| ICS 206 - Medical Plan | | | | Prepared By Dawn Jones, Updated 11/01/2016 10:31 GMT -6:00 PP | | | | |
| INCIDENT ACTION PLAN SOFTWARE™ | | Printed 11/01/2016 11:42 GMT -6:00 | | Page 12 of 14 | | © TRG | | |

ICS 207 - Organization Chart

Version Name: 20161101_Operations_Days

Incident Name: CR-251

Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45]



ICS 207 - Organization Chart

Version Name: 20161101_Overall_Days

Incident Name: CR-251

Period: Initial Re [10/31/2016 16:45 - 11/01/2016 16:45]

